

PROBLEM FURNACES

- Brand: Mueller Climatrol
 - Model: prefix 140-149; suffixes 75 and higher
- Brand: Lennox model #'s beginning with G8, G9, G10, G11, G12
 - Heat exchangers cracking at curve
 - These are older furnaces
- Brand: Heil, Whirlpool, Tempstar, Dayton, Sears
 - Model: NUGK, NULK, NUDK, NDLK, NRLF, NRGH, NRGF, NUGE, NDGE, NULE
 - Burner problems
 - Serial numbers L9023 and lower

FURNACE RECALLS

<u>Manufacturer</u>	<u>Model Numbers</u>	<u>Serial Number</u>
Rheem [electric furnaces]	REBA, UBEA, WBEA, WBEMA	M3592 to M4595
Rheem [electric air handlers]	RBHA, UBHA, WBHA, WBHMA	M3592 to M4595

<u>Trade Name</u>	<u>Brand Name</u>	<u>Model Numbers</u>	<u>Phone Number</u>
Amana Refrigeration	Energy Command	EGHW 100DA-3	800-843-0309

Safety Concern: AzCabinet insulation deterioration. Call local contractor or 717-771-6418

Brand: York
Model: P2DP
Serial: EECM – EGEM

Lennox Pulse Furnace Inspection Program

Brand: Lennox Pulse Furnace, built before 1/1/90
Model: G14 or GSR 14
Problem: Heat exchangers are cracking
What to do: Have customer contact their local dealer

Vent Pipes for natural gas or propane furnaces and boilers

HTVP – High temperature Plastic Vent Pipes recall. Vent pipes are plastic; the vent pipes are gray or black in color; the vent pipes have names "PLEXVENT", "PLEXVENT II" OR "ULTRAVENT" stamped on the vent pipe or printed on stickers places on pieces used to connect the pipes together. Call 800-758-3688.

Furnace Upgrades

Brand: Heil/Whirlpool/Tempstar
Model: NUGK serial number H540 and lower

Brand: Armstrong/Magic Chef
Model: EG6B – EG7B [all serial numbers]

This information has been prepared from multiple sources and is believed to be as accurate as possible. However, it is for information only, and I recommend that readers check with their preferred HVAC contractor for possible updates if they have any questions about their particular systems.